



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3916-041
Job Sheet 193840



Part No: D3916-041

Job Qty: 6 pcs

Part Name: Rib Assembly



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 4/23/19

Job Tracking No:

Due Date: 5/6/19

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG REV A IPP RevA: New issue DD verified by:EC IPP Rev:B as per dwg revA 10.03.15 verified by:EC
Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Large Fab - Basket - 1	6 pcs	5/6/19		0.00	2.94	Large Fab - 1		
							Large Fab - 10		
							Large Fab - 2		
							Large Fab - 3		
							Large Fab - 4		
							Large Fab - 5		
							Large Fab - 6		
							Large Fab - 7		
							Large Fab - 8		MAE
105	QC 5	6 pcs	5/6/19		0.00	0.00	Large Fab - 9		
							QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22		
							QC 5 - 24		
							QC 5 - 3		
							QC 5 - 43		
							QC 5 - 49		
							QC 5 - 51		
							QC 5 - 58		
							QC 5 - 68		
							QC 5 - 9		
							QC 5 - 50		EL
							QC 5 - 30		
							QC 5 - 40		
107	Large Fab - Basket - 2 - B4B	6 pcs	5/6/19		0.00	4.00	Large Fab - 1 - B4B		
							Large Fab - 10 - B4B		
							Large Fab - 2 - B4B		
							Large Fab - 3 - B4B		

Plex 4/23/19 10:26 AM Dart.lajeunesse.marie

					Large Fab - 4 - B4B	
					Large Fab - 5 - B4B	
					Large Fab - 6 - B4B	
					Large Fab - 7 - B4B	CC
					Large Fab - 8 - B4B	
					Large Fab - 9 - B4B	
110	QC 5	6 pcs	5/6/19	0.00 0.00	QC 5 - 10	
					QC 5 - 12	
					QC 5 - 17	
					QC 5 - 18	
					QC 5 - 19	
					QC 5 - 22	
					QC 5 - 24	
					QC 5 - 3	DAS
					QC 5 - 43	43
					QC 5 - 49	9-89
					QC 5 - 51	
					QC 5 - 58	
					QC 5 - 68	
					QC 5 - 9	
					QC 5 - 50	
					QC 5 - 30	
					QC 5 - 40	
120	QC 10	6 pcs	5/6/19	0.00 0.00	QC 10 - 10	
					QC 10 - 18	
					QC 10 - 24	
					QC 10 - 43	DAS
					QC 10 - 50	43
					QC 10 - 58	9-89
					QC 10 - 9	
130	Packaging 3-1 - Stock - B4B	6 pcs	5/6/19	0.00 0.00	Packaging 3 - 1 - B4B	
					Packaging 3 - 2 - B4B	
					Packaging 3 - 3 - B4B	
					Packaging 3 - 4 - B4B	
					Packaging 3 - 5 - B4B	
					Packaging 3 - 6 - B4B	
					Packaging 3 - 7 - B4B	
					Packaging 3 - 8 - B4B	
					Packaging 3 - 9 - B4B	
					Packaging 3 - 10 - B4B	
					Packaging 3 - 11 - B4B	
					Packaging 3 - 12 - B4B	
					Packaging 3 - 13 - B4B	
					Packaging 3 - 14 - B4B	
					Packaging 3 - 15 - B4B	
					Packaging 3 - 16 - B4B	
					Packaging 3 - 17 - B4B	
					Packaging 3 - 18 - B4B	
					Packaging 3 - 19 - B4B	DAS
					Packaging 3 - 20 - B4B	43
					Packaging 3 - 21 - B4B	9-89
					Packaging 3 - 22 - B4B	
					Packaging 3 - 23 - B4B	
					Packaging 3 - 24 - B4B	
					Packaging 3 - 25 - B4B	
					Packaging 3 - 26 - B4B	
					Packaging 3 - 27 - B4B	
					Packaging 3 - 28 - B4B	
					Packaging 3 - 29 - B4B	

Plex 4/23/19 10:26 AM Dart.lajeunesse.marie

				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
140	QC 21 - SA	6 pcs	5/6/19	0.00 0.00	QC 21 - SA - 21
					QC 21 - SA - 70
					QC 21 - SA - 53

DAS
21
8-89
MAY 09 2019

Part Op 100 - 1- Cut tube 50" 2- Bend tube with manuel pipe bender as per DT9567 *** Make line at 9.00" and use jig for other
 Descriptions: lines, and ensure seam in place on side of tube when bending*** 3- Trim access tube material to finish size as per dwg
 D3916 4- Drill and chamfer holes as per dwg D3916-1 using DT9605
 105 - (QC5- Inspect part completeness to step on W/O)
 107 - (Weld per dwg A/R S.S. rod Batch:) 1- weld bushing as per dwg D3916 2- grind welds flush
 110 - (QC5- Inspect part completeness to step on W/O)
 120 - (QC10- Inspect visual per QSI004- ground welds)
 130 - (Identify as per dwg & Stock Location:) LOCATION: WA004-5
 140 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D3759-1	Bushing	42 pcs (7 ea)	100-Large Fab - Basket - 1	5176865
M304TS0.750W.049	304 Sq Tube .75X.75X.049W	24.9960 ft (4.166 ea)	100-Large Fab - Basket - 1	5177779

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
		42	25	0
		25	143	0



Container No: 5178465



Part: D3916 - 0

Job No: 193840

Serial No/Batch: 5178465

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Dart Aerospace Ltd.
 1270 Aberdeen Street
 Hawkesbury, ON K64 1K7
 CANADA
 TEL.: 1 613 632-5200
 Email: sales@dartaero.com
 www.dartaerospace.com

Date: 05/07/19

tions

ot be found.

Plex 4/23/19 10:26 AM Dart.lajeunesse.marie

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042) Completed By _____ Lead hand / Supervisor _____ QC / QA Coordinator _____	
Description Work Order Deviation		Disposition			
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
		Other/Details:			